

H CLASS EQUIPMENT SERVICING -CLIENT REQUIREMENTS

NOTE: Your H Class Equipment must be prepared in the below manner to be accepted for service and avoid rejection by our technicians.

H CLASS VACUUM CLEANERS

STEP 1 STEP 2 STEP 3 DO NOT SEND VACUUM HOSES. TOOLS. ENSURE VACUUM 1st Bagging: CAUT ON WANDS OR ACCESSORIES **INTAKE & EXHAUST** PLACE VACUUM ASBE INTO NEW. CLEAN CAPS ARE IN PLACE. WET WIPE VACUUM ASBESTOS WASTE 0 BAG DOWN THOROUGH-LY TO ENSURE IT IS AUTION **ESTO** DECONTAMINATED **STEP 6 STEP 4 STEP 5** 2nd Bagging: 2nd Bagging: **1st Bagging:** CAUTION **CLOSE BAG &** PLACE BAGGED AGAIN - CLOSE BESTOS 2nd BAG & GOOSE **GOOSE NECK TOP** VACUUM INTO NECK TOP OF BAG **OF BAG AND USE** 2nd NEW, CLEAN DUCT TAPE TO ASBESTOS WASTE AND USE DUCT SECURE & SHUT TAPE TO SECURE BAG ITIO UTION UTION ESTO & SHUT OFF! OFF! STO

YOUR H CLASS VACUUM CLEANER IS NOW OK TO BE DROPPED IN FOR SERVICING!

STEP 7	STEP 8	STEP 9	STEP 10
PLACE DOUBLE BAGGED VACUUM INTO SEALED CARTON OR CONTAINER. MARK WITH "DANGER ASBESTOS DUST" LABEL!	<form><form></form></form>	MISCELLANEOUS DANGEROUS 9 9 FURTHER MARK CARTON WITH A "MISCELLANEOUS DANGERS GOODS 9 DIAMOND" STICKER	
BRISBANE Address: 2 / 44 Musgrave Rd Coopers Plains QLD Phone: (07) 3277 3197	SY Address: 3 Metters Pl Wetherill Pa Phone: (02) 8103 50	ark NSW	MELBOURNE 72 North View Drive Sunshine West VIC (03) 9081 0172

Email service@assuredequipment.com.au Mon-Fri 7.30am - 4.00pm Hours Web:

Email Hours: Web:

service@assuredequipment.com.au Mon-Fri 8.00am - 5.00pm

	MELBOOK
ddress:	72 North View Drive
	Sunshine West VIC
hone:	(03) 9081 0172
mail:	service@assuredequ
ours:	Mon-Fri 7.30am - 4.30
/eb:	www.assuredequipm

pment.com.au

pm